

Service Bulletin #68RFE

Attention: Instructions mistake

Tightening instructions for #68RFE transmission pans: s/n 0000 to s/n 350 **could have Incorrect Torque Specs!** These specs are for the pan mounting bolts.

The correct torques specs are (105 in lbs) or 7-9 ft lbs.

The **WRONG Specs. call for 12-16 ft lbs.** This is in two places and is wrong in both places.

Please take note and tighten with caution: Do Not Over Tighten. Failure to take note will result in stripping bolt threads in the transmission case.